








Assembly instructions for the exhibition stand I100




Important

Pointed screws must be used for all profiles with screw holes.


1. Mount the bottom cross profiles including the pointed screws to form the corner.




2. Then mount the cross profiles.




3. Mount the required lower cross profiles including pointed screws.




4. Then mount the cross profiles and insert the bolts in the profile.



5. Push the top profiles onto the bolts. Ensure that the holes face upward.



6. Then mount the cross profiles including the pointed screws.



7. Fully assembled exhibition stand.
If necessary, use the adjustable feet to compensate for unevenness in the floor.

