














Assembly instructions for the exhibition stand I103




Important

Pointed screws must be used for all profiles with screw holes.


1. Mount the bottom cross profiles including the pointed screws to form the corner.




2. Insert the lower panels with the H-profiles and then mount the cross profiles.




3. Mount the required lower cross profiles including pointed screws.




4. Insert the remaining panels with the H-profiles one after the other and then mount the cross profiles.




5. Insert the bolts in the profile.




6. Push the top profiles onto the bolts.
Ensure that the holes face upward.



7. Insert the upper panels with the H-profiles one after the other and then mount the cross profiles including the pointed screws.



8. Then mount the fascia sign frame



8. Fully assembled exhibition stand.
If necessary, use the adjustable feet
to compensate for unevenness in the floor.

